01-Feb-26	DAILY MAINTENANCE REPORT										
S/N	**Asset Code**	**Description**	**Date of B/D**	**BD Days**	**Location**	**Breakdown Reason**	**Components**	**Technicians**	**Duration**	**Status**	**Maintained**
HCV: 4											
1	321 39 132	Tata-10 wheeler	30-Dec-25	52	WORKSHOP	Propeller Shaft Sleeve Yoke and Pinion Flange failure. Drivetrain disconnected; Replacement of slip-joint assembly; Final checks tomorrow initial hours	Sleeve yoke,pinion flange, bearings and fabricated cone and cylindrical washers	Arjun, Manish, Balmukunda, Ajesh	7 hrs	Pending	26-Dec-25
2	321 39 134	Eicher-10 wheeler	1-Feb-26	19	WORKSHOP	Battery terminal wire refabricated, air filter element cleaned; Radiator pipe slippage issue attended		Manish, Ram, Sagar	4 hrs	Completed	28-Jan-26
3	321 39 141	TATA Lowbed	1-Feb-26	19	WORKSHOP	Tyre replaced with new unit and greased; FR head lamp issue resolved	Tyre, Grease	Arjun, Manish, Ram	2 hrs	Completed	-
4	GA1KA5507	CRANE-SANIMA	1-Feb-26	19	WORKSHOP	Tyre pressure checked and refilled and greased	Grease	Manish	30 min	Completed	-
Excavator: 1											
5	321 45 16	Excavator 360 (Hyundai)	17-Jan-26	34	WORKSHOP	Pump assy and injector nozzle issue; attended, final checks tomorrow	Repaired fuel pump and nozzle	Ram, Kedar, Balmukunda	4 hrs	Pending	9-Jan-26
Light vehicle: 1											
6	321 44 30	Mahindra Bolero	1-Feb-26	19	WORKSHOP	New tyre replaced, brake linings inspected and greased	Tyre, Grease	Sagar	1.5 hrs	Completed	25-Jan-26
Tractor: 2											
7	321 38 29	Tractor Newholland	1-Feb-26	19	WORKSHOP	Starting issue resolved twice; Battery replacement needed		Ram	30 min	Completed	28-Jan-26
8	321 38 31	Tractor Arjun- Mahendra	1-Feb-26	19	WORKSHOP	Punctured tyre repaired and kept for safekeeping		Arjun	1 hr	Completed	31-Jan-26
Grader: 1											
9		HIDROMEK MG 430	1-Feb-26	19	WORKSHOP	Steering cylinder lock issue resolved using makeshift solution and greased; parts to order	Grease, Electrodes	Balmukunda, Arjun, Manish, Sagar	2 hrs	Completed	22-Jan-26
Rock Hammer Breaker: 1											
10	321 17 07	Breaker hammer	31-Jan-26	20	WORKSHOP	Breaker piston bush replaced, final touchup tomorrow initial hours		Kedar, Sagar	4 hrs	Pending	-

02-Feb-26	DAILY MAINTENANCE REPORT										
S/N	**Asset Code**	**Description**	**Date of B/D**	**BD Days**	**Location**	**Breakdown Reason**	**Components**	**Technicians**	**Duration**	**Status**	**Maintained**
HCV: 7											
1	321 39 132	Tata-10 wheeler	30-Dec-25	52	WORKSHOP	Propeller Shaft Sleeve Yoke and Pinion Flange failure. Drivetrain disconnected; Replacement of slip-joint assembly completed		Arjun, Ram, Manish	3.5 hrs	Completed	26-Dec-25
2	321 39 110	Eicher-10 wheeler	2-Feb-26	18	WORKSHOP	Fuel tank assy leakage issue; order placed				Pending	31-Jan-26
3	321 39 134	Eicher-10 wheeler	2-Feb-26	18	WORKSHOP	Coolant replenished by 5L; check light issue attended	Coolant	Sagar, Ram	30 min	Completed	1-Feb-26
4	321 39 107	Eicher-10 wheeler	2-Feb-26	18	WORKSHOP	Radiatory assy mounting frame welded and repaired; radiator assy hose issue resolved	Electrodes	Anil, Balmukunda	30 min	Completed	31-Jan-26
5	321 39 139	Eicher-10 wheeler	2-Feb-26	18	WORKSHOP	Startor assy replaced from 321 39 124	Salvaged self	Ram	1 hr	Completed	30-Jan-26
6	321 39 111	Eicher-6 wheeler	2-Feb-26	18	WORKSHOP	Puncture successfully repaired and inner-liner integrity restored.		Manish	1 hr	Completed	31-Jan-26
7	321 39 97	Eicher-10 wheeler	2-Feb-26	18	WORKSHOP	Faulty dual delivery unit replaced with new unit	DDU repair kit	Balmukunda	5 hrs	Completed	30-Jan-26
Excavator: 1											
8	321 45 19	Komatsu Excavator PC-210	2-Feb-26	18	WORKSHOP	Track chain bolts removed and replaced	25 RH 9 LH Track bolts	Ram, Sagar, Anil	5 hrs	Pending	29-Jan-26
Light vehicle: 2											
9	LUPR01001CHA3504	Mahindra Bolero	2-Feb-26	18	WORKSHOP	Stabilizer bar bush and link bush changed	D bush, Link bush	Arjun	30 min	Completed	22-Jan-26
10	341 03 43	MAHINDRA BOLERO	2-Feb-26	18	WORKSHOP	Full servicing completed, propeller shaft yoke and teeth replaced	Engine oil, oil filter, air filter, yoke and teeth, Grease	Arjun, Binod	3.5 hrs	Completed	30-Jan-26
Rock Hammer Breaker: 2											
11	321 17 07	Breaker hammer	31-Jan-26	20	WORKSHOP	All bolts tightened; Nitrogen gas replenished	N2, Side plate bolts	Kedar, Manish	2 hrs	Completed	-
12	-	Breaker hammer	2-Feb-26	18	WORKSHOP	Housing removed		Kedar, Manish, Binod	45 min	Pending	-

03-Feb-26	DAILY MAINTENANCE REPORT										
S/N	**Asset Code**	**Description**	**Date of B/D**	**BD Days**	**Location**	**Breakdown Reason**	**Components**	**Technicians**	**Duration**	**Status**	**Maintained**
HCV: 6											
1	321 39 110	Eicher-10 wheeler	2-Feb-26	18	WORKSHOP	Fuel tank assy leakage issue; under maintenance	Silicon paste, Fevi quick	Manish	1.5 hrs	Pending	31-Jan-26
2	321 39 125	Mini Truck SML (4 Wheeler)	3-Feb-26	17	WORKSHOP	Horn and battery issue resolved		Ram	45 min	Completed	11-Jan-26
3	321 39 107	Eicher-10 wheeler	3-Feb-26	17	WORKSHOP	Trunnion & Clevis mounting brackets welded and repaired	Electrodes	Anil	1 hr	Completed	2-Feb-26
4	321 39 93	Eicher-6 wheeler	3-Feb-26	2	WORKSHOP	Battery issue attended		Ram	15 min	Completed	31-Jan-26
5	321 39 159	Tata-10 wheeler	3-Feb-26	0	WORKSHOP	Brakes adjusted and tyre pressure maintained		Arjun	20 min	Completed	28-Dec-25
6	321 39 134	Eicher-10 wheeler	3-Feb-26	17	WORKSHOP	RR RH Tyre puncture repaired		Arjun, Manish	1.5 hr	Completed	2-Feb-26
Excavator: 8											
7	321 45 25	Hyundai Excavator 220LS	24-Dec-25	58	CRUSHER	Track chain dislodged; idler, sprockets, link bushes, and seals replacement required; items received; Under maintenance	Sprocket	Sagar, Anil, Binod	4 hrs	Pending	22-Dec-25
8	321 45 16	Excavator 360 (Hyundai)	17-Jan-26	34	WORKSHOP	Pump assy and injector nozzle issue; under maintenance, filter parts to replace	Repaired fuel pump and nozzle	Ram, Kedar, Balmukunda	4 hrs	Pending	9-Jan-26
9	321 45 19	Komatsu Excavator PC-210	2-Feb-26	18	WORKSHOP	Track chain bolts removed and replaced; door hinge repaired and Greased; Hose burst valve leakage issue resolved	25 RH 40 LH Track bolts, Grease	Ram, Sagar, Anil, Binod, Kedar	2 hrs	Completed	29-Jan-26
10	321 45 21	Komatsu Excavator PC-210	3-Feb-26	17	ADIT	Preventive lubrication was applied to all critical pivot assemblies, linkages, and fittings.	Grease	Binod	15 min	Completed	31-Jan-26
11	321 45 43	CAT Excavator 323D3	3-Feb-26	17	CRUSHER	Scheduled lubrication completed for all pivot points, linkages, and fittings.	Grease	Binod	15 min	Completed	29-Jan-26
12	321 45 38	Komatsu Excavator PC-210	3-Feb-26	17	ADIT	All moving joints, pivot points, and fittings received proper lubrication.	Grease	Binod	15 min	Completed	29-Jan-26
13	321 45 40	CAT Excavator 323D3	3-Feb-26	17	MAT	All articulated joints, linkages, and fittings were lubricated as per standard practice.	Grease	Binod	15 min	Completed	26-Jan-26
14	321 45 42	CAT Excavator 323D3	3-Feb-26	17	THAUWA	Comprehensive lubrication of all moving components completed	Grease	Binod	15 min	Completed	17-Jan-26
Wheel Loader: 2											
15	321 44 45	Wheel Loader-Lonking	3-Feb-26	17	WORKSHOP	Tyre puncture repaired	Tube	Arjun, Ram, Manish	2.5 hrs	Completed	28-Jan-26
16	321 44 47	Wheel Loader-Lonking	3-Feb-26	17	TRT	Adaptor and teeth replaced	Adaptor, Bucket teeth	Raymon	2 hrs	Completed	31-Jan-26
Rock Hammer Breaker: 2											
17	-	Breaker hammer	2-Feb-26	18	WORKSHOP	Housing removed; welding; under maintenance	Electrodes	Nar	3 hrs	Pending	-
18	-	Breaker hammer	3-Feb-26	17	WORKSHOP	Under maintenance; to be tested on m/c tomorrow initial hours	N2	Kedar, Manish		Pending	-
Backhoe: 2											
19	321 44 49	Backhoe-JCB	3-Feb-26	17	WORKSHOP	Lubricants applied to all pivot assemblies, linkages, and fittings	Grease	Binod	30 min	Completed	28-Jan-26
20	321 44 40	Backhoe-Bull	3-Feb-26	17	WORKSHOP	Full lubrication of pivot assemblies, linkages, and grease points completed.	Grease	Binod	30 min	Completed	29-Jan-26

04-Feb-26	DAILY MAINTENANCE REPORT										
S/N	**Asset Code**	**Description**	**Date of B/D**	**BD Days**	**Location**	**Breakdown Reason**	**Components**	**Technicians**	**Duration**	**Status**	**Maintained**
HCV: 6											
1	321 39 134	Eicher-10 wheeler	3-Feb-26	17	WORKSHOP	RR LH Tyre puncture repaired, Buggy repaired; Both LH RH Tie rod ends repair kit replaced	Tyre, Electrodes; tie rod repair kits	Arjun, Manish, Nar	6.5 hrs	Completed	2-Feb-26
2	321 39 107	Eicher-10 wheeler	4-Feb-26	16	WORKSHOP	Brakes adjusted		Arjun	15 min	Completed	3-Feb-26
3	321 39 97	Eicher-10 wheeler	4-Feb-26	16	WORKSHOP	Tyre rotation & New tyre replaced	Tyre	Balmukunda	1.5 hrs	Completed	2-Feb-26
4	321 39 132	Tata-10 wheeler	4-Feb-26	16	WORKSHOP	Starting issue detected; Startor assy replaced; Tail pinion bearings found to be replaced again	Repaired Self	Ram, Balmukunda	2.5 hr	Pending	30-Dec-25
5	321 39 133	Tata-10 wheeler	4-Feb-26	16	WORKSHOP	Tyre puncture issue; leaf springs to change; under maintenance		Arjun, Manish	1 hr	Pending	29-Jan-26
6	321 39 111	Eicher-6 wheeler	4-Feb-26	16	WORKSHOP	FR head lamp issue attended		Ram	30 min	Completed	2-Feb-26
Excavator: 4											
7	321 45 25	Hyundai Excavator 220LS	24-Dec-25	58	CRUSHER	Track chain dislodged; idler, sprockets, link bushes, and seals replacement required; items received; Under maintenance	Idler	Sagar, Anil, Binod	5 hrs	Pending	22-Dec-25
8	321 45 19	Komatsu Excavator PC-210	4-Feb-26	16	RIVERBED	Hydraulic oil replenished by 9L; 2 new bucket teeths locks fabricated and installed	Hydraulic oil, Bucket teeth locks	Ram, Sagar	1 hr	Completed	3-Feb-26
9	321 45 39	Kobelco Excavator SK220	4-Feb-26	16	THUMBA	Comprehensive lubrication of all moving components completed	Grease	Sagar, Binod	25 min	Completed	28-Jan-26
10	321 45 29	XCMG Excavator 215C	4-Feb-26	16	THUMBA	Lubricated all joints	Grease	Sagar, Binod	20 min	Completed	28-Jan-26
Rock Hammer Breaker: 2											
11	-	Breaker hammer	2-Feb-26	18	WORKSHOP	Welding completed; under maintenance	Electrodes	Nar	3 hrs	Pending	-
12	-	Breaker hammer	3-Feb-26	17	THUMBA	Tested on asset 321 45 39; Under maintenance		Balmukunda, Sagar, Binod	1.5 hrs	Pending	-
Backhoe: 1											
13	321 44 49	Backhoe-JCB	4-Feb-26	16	WORKSHOP	Tyre puncture repaired		Arjun, Manish	1.5 hr	Completed	3-Feb-26
Light vehicle: 4											
14	321 44 38	Mahindra Bolero	4-Feb-26	16	WORKSHOP	Gear box overhauled	Clutch set, Brake oil	Ram, Balmukunda	6.5 hrs	Completed	31-Jan-26
15	GA4CHA1930	Mahindra Bolero	4-Feb-26	16	WORKSHOP	Lubricants applied to all pivot assemblies, linkages, and fittings	Grease	Balmukunda	15 min	Completed	31-Jan-26
16	321 44 30	Mahindra Bolero	4-Feb-26	16	WORKSHOP	Tyre pressure relieved		Manish	15 min	Completed	1-Feb-26
17	LUPR01001CHA3504	Mahindra Bolero	2-Feb-26	18	WORKSHOP	Lubricants applied to all pivot assemblies, linkages, and fittings	Grease	Arjun	15 min	Completed	22-Jan-26

05-Feb-26		DAILY MAINTENANCE REPORT						M-Techs: 2	E-Tech: 1	L-Tech: 1	W-Tech: 2
S/N	Asset Code	Description	Date of B/D	BD Days	Location	Breakdown Reason	Components	Technicians	Duration	Status	Maintained
High Commercial Vehicle (HCV): 6											
1	321 39 133	Tata-10 wheeler	4-Feb-26	16	WORKSHOP	Tyre puncture issue; lwr leaf springs changed, 2 new tyres fitted	Tyres	Balmukunda, Arjun, Binod	6 hrs	Completed	29-Jan-26
2	321 39 134	Eicher-10 wheeler	5-Feb-26	15	WORKSHOP	FR LH RH Cushion engine supports replaced	Cushion supports	Arjun, Binod	3.5 hrs	Completed	4-Feb-26
3	321 39 125	Mini Truck SML (4 Wheeler)	5-Feb-26	15	WORKSHOP	New tyre replaced	Tyre	Binod	45 min	Completed	3-Feb-26
4	321 39 107	Eicher-10 wheeler	5-Feb-26	15	WORKSHOP	Wiper assy switch issue, no stock, Head lamp issue resolved		Ram	3 hrs	Completed	4-Feb-26
5	321 39 97	Eicher-10 wheeler	5-Feb-26	15	WORKSHOP	Scheduled lubrication completed for all pivot points, linkages, and fittings.	Grease	Binod	20 min	Completed	4-Feb-26
6	321 39 128	Lowbed	5-Feb-26	15	DHOVAN	RR propeller shaft UJ cross damaged; under maintenance		Arjun, Binod	4 hrs	Completed	4-Feb-26
Light Commercial Vehicle (LCV): 3											
7	LUPR01001CHA3504	Mahindra Bolero	5-Feb-26	15	WORKSHOP	Tyres replaced	Tyre	Arjun	15 min	Completed	2-Feb-26
8	341 03 40	Mahindra Bolero	5-Feb-26	15	WORKSHOP	RR brake pipe repaired	Salvaged brake pipe	Balmukunda	40 min	Completed	23-Jan-26
9	PR301024CHA9018	Toyota hilux	5-Feb-26	15	WORKSHOP	Brake shoe replaced	Brake shoe	Balmukunda	1 hr	Completed	-
Hydraulic Excavator (HE): 2											
10	321 45 21	Komatsu Excavator PC-210	5-Feb-26	15	ZEROKILO	Breaker chisel repaired; to be mounted tomorrow inital hours	Electrodes	Balmukunda, Anil	2.5 hrs	Completed	3-Feb-26
11	321 45 40	CAT Excavator 323D3	5-Feb-26	15	TRT	Structural failure of the upper carriage housing and cooling pack due to high-velocity impact from a ceiling rockfall; shifted to workshop and under maintenance		Ram, Anil	4 hrs	Pending	3-Feb-26
Rock Hammer Breaker: 1											
12	-	Breaker hammer	3-Feb-26	17	WORKSHOP	Tested on asset 321 45 39; Sent to tapethok		Balmukunda	30 min	Completed	-

06-Feb-26	DAILY MAINTENANCE REPORT M-tech = Mechanical Technician E-Tech = Auto Electrician L-Tech = Lube W-Tech = Welder						M-Techs: 2	E-Tech: 1	L-Tech: 1	W-Tech: 2
S/N	**Asset Code**	**Description**	**Date of B/D**	**BD Days**	**Location**	**Breakdown Reason**	**Components**	**Technicians**	**Duration**	**Status**	**Maintained**
High Commercial Vehicle (HCV): 6											
1	321 39 128	Lowbed	5-Feb-26	15	DHOVAN	RR propeller shaft UJ cross damaged-Maintenance completed	Uj cross	Arjun, Binod	4.5 hrs	Completed	4-Feb-26
2	321 39 139	Eicher-10 wheeler	6-Feb-26	14	WORKSHOP	Preventive lubrication was applied to all critical pivot assemblies, linkages, and fittings.	Grease	Binod	20 min	Completed	2-Feb-26
3	321 39 107	Eicher-10 wheeler	6-Feb-26	14	WORKSHOP	New tyre replaced	Tyre	Binod, Balmukunda	2 hrs	Completed	4-Feb-26
4	321 39 111	Eicher-6 wheeler	6-Feb-26	14	WORKSHOP	Rear buggy locks fabricated	Electrodes	Nar	1 hr	Completed	4-Feb-26
5	321 39 93	Eicher-6 wheeler	6-Feb-26	14	WORKSHOP	Brake linings changed	Brake linings	Arjun	1.5 hrs	Completed	3-Feb-26
6	321 39 86	Eicher-6 wheeler	6-Feb-26	14	WORKSHOP	Alternate (used) alternator fitted		Ram	40 min	Pending	-
Light Commercial Vehicle (LCV): 1											
7	GA4CHA1930	Mahindra Bolero	6-Feb-26	14	WORKSHOP	Multiple Tyres replaced	Tyres	Binod	1.5 hr	Completed	2-Feb-26
Hydraulic Excavator (HE): 2											
8	321 45 40	CAT Excavator 323D3	5-Feb-26	15	TRT	Structural failure of the upper carriage housing and cooling pack due to high-velocity impact from a ceiling rockfall; shifted to workshop and under maintenance		Ram, Anil	4 hrs	Pending	3-Feb-26
9	321 45 29	XCMG Excavator 215C	6-Feb-26	14	THUMBA	Undercarriage maintenance under progress		Undercarriage Technicians	Full day	Completed	4-Feb-26
Backhoe: 1											
10	321 44 40	Backhoe-Bull	6-Feb-26	14	WORKSHOP	Full lubrication of pivot assemblies, linkages, and grease points completed.	Grease	Binod	30 min	Completed	3-Feb-26
Transit Mixture: 1											
11	321 39 145	TATA putzmeister Mixture	6-Feb-26	14	WORKSHOP	Fabricated hopper removed		Anil, Nar	2.5 hrs	Completed	27-Dec-25
Shotcrete Machine: 1											
12	321 19 75	Robert Shotcrete-Putzmeister	6-Feb-26	14	TRT	Relay unit tested; Starting issue resolved; Nozzle point ckts issue resolved; Hydraulic leakage temporarily arrested using a makeshift remedy & replenished for the same	Hydraulic Oil 8L	Ram, Balmukunda	4.5 hrs	Completed	31-Jan-26

07-Feb-26	DAILY MAINTENANCE REPORT							M-Techs: 4	E-Tech: 1	L-Tech: 1	W-Tech: 3
	M-tech = Mechanical Technician E-Tech = Auto Electrician L-Tech = Lube W-Tech = Welder										
S/N	**Asset Code**	**Description**	**Date of B/D**	**BD Days**	**Location**	**Breakdown Reason**	**Components**	**Technicians**	**Duration**	**Status**	**Maintained**
High Commercial Vehicle (HCV): 4											
1	321 39 86	Eicher-6 wheeler	6-Feb-26	14	WORKSHOP	Repaired self fitted	Repaired startor assy	Ram	40 min	Pending	-
2	321 39 133	Tata-10 wheeler	7-Feb-26	13	WORKSHOP	Rear buggy repaired; mobile replenished by 5L	Engine oil, Electrodes	Manish, Raymond	2 hrs	Completed	4-Feb-26
3	321 39 134	Eicher-10 wheeler	7-Feb-26	13	WORKSHOP	Headlight bulb issue resolved	Bulb	Ram	45 min	Completed	4-Feb-26
4	321 39 107	Eicher-10 wheeler	7-Feb-26	13	TRT	Tyre puncture issue; to be mended tomorrow initial hours				Pending	6-Feb-26
Light Commercial Vehicle (LCV): 5											
5	GA4CHA1930	Mahindra Bolero	7-Feb-26	13	WORKSHOP	Tyre puncture repaired		Arjun	1 hr	Completed	2-Feb-26
6	341 03 40	Mahindra Bolero	7-Feb-26	13	WORKSHOP	Rear brakes issue resolved		Arjun	1 hr	Completed	5-Feb-26
7	BAP0103CHA 7849	Mahindra Bolero	7-Feb-26	13	WORKSHOP	Comprehensive lubrication of all moving components completed	Grease	Binod	15 min	Completed	5-Feb-26
8	BA21CHA108	Mahindra Bolero	7-Feb-26	13	WORKSHOP	All moving joints, pivot points, and fittings received proper lubrication.	Grease	Binod	15 min	Completed	5-Feb-26
9	BA1GA1853	TATA-APF	7-Feb-26	13	WORKSHOP	Tappid gaskit changed, cabin mounting replaced; steering cross assy changed and greased	Tappit gaskit, cabin mounting, steering cross	Arjun, Ram, Manish	5 hrs	Completed	-
Hydraulic Excavator (HE): 5											
10	321 45 25	Hyundai Excavator 220LS	24-Dec-25	58	MAT	Track chain dislodged; idler, sprockets, link bushes, and seals replacement required; items received; Under maintenance	Track link,Track nut & bolts	Sagar, Anil, Binod	5 hrs	Pending	22-Dec-25
11	321 45 16	Excavator 360 (Hyundai)	17-Jan-26	34	WORKSHOP	Pump assy and injector nozzle issue; Preventive maintenance servicing was carried out and finalized; Load retention still observed in the arm cylinder; return valve inspection carried out;final inspections tomorrow initial hours	Engine oil, Engine oil filter, fuel filters, Hydraulic oil	Balmukunda, Manish	9.5 hrs	Completed	9-Jan-26
12	321 45 40	CAT Excavator 323D3	5-Feb-26	15	WORKSHOP	Structural failure of the upper carriage housing and cooling pack due to high-velocity impact from a ceiling rockfall; shifted to workshop, radiator repaired, Greased-maintenance completed	Resibond, Bond tite, Grease	Ram	3 hrs	Completed	3-Feb-26
13	321 45 39	Kobelco Excavator SK220	7-Feb-26	13	THUMBA	Bucket replaced from breaker	Repaired bucket, Shims, Lockpins	Sagar, Anil	1 hr	Completed	4-Feb-26
14	321 45 41	CAT Excavator 323D3	7-Feb-26	13	WORKSHOP	Bucket teeth replaced	Salvaged teeth	Arjun	20 min	Completed	29-Jan-26
Backhoe: 1											
15	321 44 49	Backhoe-JCB	7-Feb-26	13	WORKSHOP	Lubricants applied to all pivot assemblies, linkages, and fittings	Grease	Binod	30 min	Completed	3-Feb-26
Transit Mixture: 1											
16	321 39 145	TATA putzmeister Mixture	6-Feb-26	14	WORKSHOP	Hardened concrete deposits within the hopper were mechanically removed		Anil	2.5 hrs	Completed	27-Dec-25

08-Feb-26	DAILY MAINTENANCE REPORT M-tech = Mechanical Technician E-Tech = Auto Electrician L-Tech = Lube W-Tech = Welder							M-Techs: 4	E-Tech: 1	L-Tech: 1	W-Tech: 3
S/N	Asset Code	Description	Date of B/D	BD Days	Location	Breakdown Reason	Components	Technicians	Duration	Status	Maintained
High Commercial Vehicle (HCV): 5											
1	321 39 114	Eicher-10 wheeler	4-Jan-26	47	WORKSHOP	Fuel pump and injector nozzles fitted		Ram, Balmukunda, Arjun	5 hrs	Pending	-
2	321 39 110	Eicher-10 wheeler	2-Feb-26	18	WORKSHOP	Fuel tank assembly leakage observed; silicone sealant (Bond-Tite) applied, however minor leakage persists; fuel tank reinstalled		Arjun, Ram	1 hr	Completed	31-Jan-26
3	321 39 107	Eicher-10 wheeler	7-Feb-26	13	TRT	Shifted to workshop;New tyre fitted, complete servicing executed, and pickup-related issue attended and resolved; Air filter assy needs replacement; placed order	Tyre, Engine oil,engine oil filter, fuel filter	Ram, Arjun, Manish	5 hrs	Completed	6-Feb-26
4	321 39 139	Eicher-10 wheeler	8-Feb-26	12	WORKSHOP	Air pressure pipe issue resolved		Balmukunda	15 min	Completed	6-Feb-26
5	321 39 93	Eicher-6 wheeler	8-Feb-26	12	WORKSHOP	FR RH strut assy brackets fabricated and installed back	Electrodes	Balmukunda	2.5 hrs	Completed	6-Feb-26
Light Commercial Vehicle (LCV): 3											
6	GA4CHA1930	Mahindra Bolero	8-Feb-26	12	WORKSHOP	New tyre replaced	Tyre	Balmukunda, Ram	1 hr	Completed	7-Feb-26
7	341 03 38	Mahindra Bolero	8-Feb-26	12	WORKSHOP	Starting issue resolved; relay needs to be replaced; placed order		Ram	45 min	Completed	4-Feb-26
8	341 03 40	Mahindra Bolero	8-Feb-26	12	WORKSHOP	Fuel pipe & leaf springs to replace; placed order				Pending	7-Feb-26
Hydraulic Excavator (HE): 9											
9	321 45 25	Hyundai Excavator 220LS	24-Dec-25	58	MAT	Track chain dislodged; idler, sprockets, link bushes, and seals replacement required; items received; Under maintenance	Track link,Track nut & bolts	Sagar, Anil, Manish	5 hrs	Pending	22-Dec-25
10	321 45 16	Excavator 360 (Hyundai)	17-Jan-26	34	WORKSHOP	Fuel pump issue persists despite completion of all corrective actions; engagement of a specialized pump repair technician is required; bucket teeths & adaptor under maintenance	Adaptor, Electrodes	Balmukunda, Nar, Raymon	4.5 hrs	Pending	9-Jan-26
11	321 45 39	Kobelco Excavator SK220	8-Feb-26	12	THUMBA	Repaired rock breaker replaced with bucket and greased	Repaired breaker	Sagar, Binod	1 hr	Completed	4-Feb-26
12	321 45 19	Komatsu Excavator PC-210	8-Feb-26	12	RIVERBED	Sidecutter bolts tightenend and greased	Grease	Sagar, Binod	20 min	Completed	4-Feb-26
13	321 45 21	Komatsu Excavator PC-210	8-Feb-26	12	ADIT	Preventive lubrication was applied to all critical pivot assemblies, linkages, and fittings.	Grease	Binod	15 min	Completed	3-Feb-26
14	321 45 43	CAT Excavator 323D3	8-Feb-26	12	CRUSHER	Scheduled lubrication completed for all pivot points, linkages, and fittings.	Grease	Binod	15 min	Completed	3-Feb-26
15	321 45 38	Komatsu Excavator PC-210	8-Feb-26	12	ADIT	All moving joints, pivot points, and fittings received proper lubrication.	Grease	Binod	15 min	Completed	3-Feb-26
16	321 45 42	CAT Excavator 323D3	8-Feb-26	12	THAUWA	Comprehensive lubrication of all moving components completed	Grease	Binod	15 min	Completed	3-Feb-26
17	321 45 44	CAT Excavator 323D3	8-Feb-26	12	ADIT	Lubricated all joints	Grease	Binod	15 min	Completed	23-Jan-26
Wheel Loader: 1											
18	321 44 45	Wheel Loader-Lonking	8-Feb-26	12	WORKSHOP	All bucket teeths replaced and greased	Bucket teeths,locks, grease	Binod	45 min	Completed	3-Feb-26

09-Feb-26	DAILY MAINTENANCE REPORT M-tech = Mechanical Technician E-Tech = Auto Electrician L-Tech = Lube W-Tech = Welder						M-Techs: 4	E-Tech: 1	L-Tech: 1	W-Tech: 3
S/N	**Asset Code**	**Description**	**Date of B/D**	**BD Days**	**Location**	**Breakdown Reason**	**Components**	**Technicians**	**Duration**	**Status**	**Maintained**
High Commercial Vehicle (HCV): 4											
1	321 39 114	Eicher-10 wheeler	4-Jan-26	47	WORKSHOP	DVB Exhaust pipe salvaged from 321 39 124, hydraulic oil repelnished by 60L, Steering oil, gear oil top up, Engine on test; Shroud and FR windshield remains for arrival, rest everything's completed	Hydraulic oil, steering oil, gear oil, DVP pipe	Ram, Balmukunda, Arjun	5 hrs	Pending	-
2	321 39 125	Mini Truck SML (4 Wheeler)	9-Feb-26	11	WORKSHOP	Suspension assemblies inspected for wear, damage, and alignment, Placed order PR No:755		Balmukunda	45 min	Completed	5-Feb-26
3	321 39 139	Eicher-10 wheeler	9-Feb-26	11	WORKSHOP	Radiator assembly leakage addressed by applying a Bondtite–Resibond compound; curing time in progress.	Bondtite	Balmukunda, Arjun	3.5 hrs	Pending	8-Feb-26
4	321 39 133	Tata-10 wheeler	9-Feb-26	11	WORKSHOP	Brakes adjusted; Kingpin bearing issue; placed order PR No: 756		Arjun, Balmukunda	40 min	Completed	7-Feb-26
Light Commercial Vehicle (LCV): 3											
5	341 03 40	Mahindra Bolero	8-Feb-26	12	WORKSHOP	Fuel tank hose pipe, leaf spring front 2nd to be changed; fuel tank issue under maintenance	Diesel tank hose pipe	Arjun,, Ram	4 hrs	Pending	7-Feb-26
6	341 03 38	Mahindra Bolero	9-Feb-26	11	WORKSHOP	Tyre puncture; New tyre replaced	Tyre	Balmukunda, Binod	2.5 hrs	Completed	8-Feb-26
7	GA4CHA1930	Mahindra Bolero	9-Feb-26	11	WORKSHOP	All moving joints, pivot points, and fittings received proper lubrication.	Grease	Binod	20 min	Completed	8-Feb-26
Hydraulic Excavator (HE): 3											
8	321 45 25	Hyundai Excavator 220LS	24-Dec-25	58	MAT	Track chain dislodged; idler, sprockets, link bushes, and seals replacement required; items received; Under maintenance	Track link,Track nut & bolts	Sagar, Anil, Manish	4 hrs	Pending	22-Dec-25
9	321 45 16	Excavator 360 (Hyundai)	17-Jan-26	34	WORKSHOP	Fuel pump issue persists despite completion of all corrective actions; engagement of a specialized pump repair technician is required; bucket teeths & adaptor under maintenance	Adaptor, Electrodes	Nar	9 hrs	Pending	9-Jan-26
10	321 45 42	CAT Excavator 323D3	9-Feb-26	11	ZEROKILO	Track link bush and pin issue resolved and greased	Track link, bush & pin, Grease	Sagar, Manish, Anil	7 hrs	Completed	8-Feb-26

10-Feb-26	DAILY MAINTENANCE REPORT M-tech = Mechanical Technician E-Tech = Auto Electrician L-Tech = Lube W-Tech = Welder							M-Techs: 5	E-Tech: 1	L-Tech: 1	W-Tech: 3
S/N	**Asset Code**	**Description**	**Date of B/D**	**BD Days**	**Location**	**Breakdown Reason**	**Components**	**Technicians**	**Duration**	**Status**	**Maintained**
High Commercial Vehicle (HCV): 6											
1	321 39 139	Eicher-10 wheeler	9-Feb-26	11	WORKSHOP	Radiator assembly leakage addressed by applying a Bondtite–Resibond compound; curing time completed, fitted back		Balmukunda	1.5 hrs	Completed	8-Feb-26
2	321 39 134	Eicher-10 wheeler	10-Feb-26	10	WORKSHOP	RR multiple diaphragms issue resolved	New and Salvaged Diaphragm	Arjun	1.5 hrs	Completed	4-Feb-26
3	321 39 110	Eicher-10 wheeler	10-Feb-26	10	WORKSHOP	Rear Diaphragm replaced; Raidator assy leakage issue again	Diaphragm	Balmukunda, Mandip	1.5 hrs	Completed	8-Feb-26
4	321 39 107	Eicher-10 wheeler	10-Feb-26	10	TRT	Pickup issue; Acc. Pedal assy issue attended and resolved; PR No:759		Balmukunda	1 hr	Completed	7-Feb-26
5	321 39 135	Eicher-10 wheeler	10-Feb-26	10	WORKSHOP	Assy glass rail changed; Headlamp issue resolved; FR 3 leaf springs replaced	Glass regulator, Leaf springs	Arjun, Manish, Ram	6 hrs	Completed	10-Jan-26
6	321 39 111	Eicher-6 wheeler	10-Feb-26	10	WORKSHOP	Brakes adjusted		Mandip	1 hr	Completed	6-Feb-26
Light Commercial Vehicle (LCV): 4											
7	341 03 40	Mahindra Bolero	8-Feb-26	12	WORKSHOP	Fuel tank hose pipe, leaf spring front 2nd &5th changed; fuel tank opener and supports fabricated and installed	Diesel tank hose pipe; leaf springs; electrodes	Raymond, Manish, Mandip	3.5 hrs	Completed	7-Feb-26
8	341 03 38	Mahindra Bolero	10-Feb-26	10	WORKSHOP	Problem with relay; All electrical wiring, starting issue resolved; PR No:749		Ram	8 hrs	Completed	9-Feb-26
9	GA4CHA1930	Mahindra Bolero	10-Feb-26	10	WORKSHOP	Suspension components were checked for serviceability and abnormalities		Balmukunda	20 min	Completed	8-Feb-26
10	341 03 43	MAHINDRA BOLERO	10-Feb-26	10	WORKSHOP	FR 3 leaf srpings changed	Leaf srpings	Mandip	3 hrs	Completed	2-Feb-26
Hydraulic Excavator (HE): 5											
11	321 45 16	Excavator 360 (Hyundai)	17-Jan-26	34	WORKSHOP	Fuel pump issue persists despite completion of all corrective actions; engagement of a specialized pump repair technician is required; bucket teeths & adaptor under maintenance	Teeths, Electrodes	Nar, Anil, Raymond	9 hrs	Pending	9-Jan-26
12	321 45 21	Komatsu Excavator PC-210	10-Feb-26	10	Surgeshaft	Damaged rock breaker swapped with repaired one and lubricated all joints	Repaired rock breaker, grease	Sagar, Binod	45 min	Completed	8-Feb-26
13	321 45 38	Komatsu Excavator PC-210	10-Feb-26	10	ADIT	Shims replaced and greased	Grease, Shims	Sagar, Binod	20 min	Completed	8-Feb-26
14	321 45 29	XCMG Excavator 215C	6-Feb-26	3	THUMBA	Undercarriage maintenance compleed		Undercarriage Technicians	Full day	Completed	4-Feb-26
15	321 45 41	CAT Excavator 323D3	7-Feb-26	13	WORKSHOP	Lubricants applied to all pivot assemblies, linkages, and fittings	Grease	Sagar, Binod	20 min	Completed	29-Jan-26
Tractor: 1											
16	321 38 29	Tractor Newholland	10-Feb-26	10	WORKSHOP	Starting issue resolved ; Battery replacement needed		Ram	30 min	Completed	1-Feb-26
Backhoe: 1											
17	321 44 40	Backhoe-Bull	10-Feb-26	10	WORKSHOP	Bucket repaired	Electrodes	Nar	30 min	Completed	6-Feb-26

11-Feb-26	DAILY MAINTENANCE REPORT M-tech = Mechanical Technician E-Tech = Auto Electrician L-Tech = Lube W-Tech = Welder							M-Techs: 6	E-Tech: 1	L-Tech: 1	W-Tech: 3
S/N	**Asset Code**	**Description**	**Date of B/D**	**BD Days**	**Location**	**Breakdown Reason**	**Components**	**Technicians**	**Duration**	**Status**	**Maintained**
High Commercial Vehicle (HCV): 6											
1	321 39 86	Eicher- 10 wheeler	6-Feb-26	14	WORKSHOP	Engine assy under maintenance		Arjun, Balmukunda, Kedar, Ram, Alek	6.5 hrs	Pending	-
2	321 39 125	Mini Truck SML (4 Wheeler)	9-Feb-26	11	WORKSHOP	Comprehensive Inspection and Servicing Performed	Engine oil,Engine oil filter, fuel filters, Air filter	Alek, Mandip	2 hrs	Completed	5-Feb-26
3	321 39 135	Eicher-10 wheeler	11-Feb-26	9	WORKSHOP	Electrical ckts issue attended		Ram	30 min	Completed	10-Feb-26
4	321 39 134	Eicher-10 wheeler	11-Feb-26	9	WORKSHOP	Tyre pressure checked and maintained		Manish, Mandip	20 min	Completed	10-Feb-26
5	321 39 107	Eicher-10 wheeler	11-Feb-26	9	TRT	Brakes adjusted		Mandip, Manish	30 min	Completed	10-Feb-26
6	321 39 103	Lowbed	11-Feb-26	9	WORKSHOP	Lamps wiring ckts checked; all suspension items inspected	Electrodes	Ram, Kedar, Nar	1.5 hrs	Completed	23-Jan-26
Light Commercial Vehicle (LCV): 2											
7	341 03 40	Mahindra Bolero	11-Feb-26	9	WORKSHOP	Rear lamps wiring issue resolved		Ram	1 hr	Completed	8-Feb-26
8	341 03 38	Mahindra Bolero	11-Feb-26	9	WORKSHOP	Starting issue;Tyre issue resolved; Steering pipe refabricated and installed		Ram, Mandip	5 hrs	Completed	10-Feb-26
Hydraulic Excavator (HE): 3											
9	321 45 25	Hyundai Excavator 220LS	24-Dec-25	58	MAT	Track chain dislodged; idler, sprockets, link bushes, and seals replacement required; items received; Under maintenance	Track link,Track nut & bolts	Sagar, Anil, Manish	4 hrs	Pending	22-Dec-25
10	321 45 16	Excavator 360 (Hyundai)	17-Jan-26	34	WORKSHOP	Fuel pump issue persists despite completion of all corrective actions; engagement of a specialized pump repair technician is required; bucket teeths & adaptor maintenance completed and fully greased	Electrodes, Grease	Nar, Binod	1 hr	Pending	9-Jan-26
11	321 45 29	XCMG Excavator 215C	11-Feb-26	9	THUMBA	Track chain tightened and greased	Grease	Binod	1.5 hrs	Completed	6-Feb-26
Tractor: 1											
12	321 38 28	Tractor Arjun- Mahendra	11-Feb-26	9	WORKSHOP	Starting issue resolved		Ram	30 min	Completed	31-Jan-26
Rock Hammer Breaker: 1											
13	-	Breaker hammer	11-Feb-26	9	WORKSHOP	Through bolt replaced, housing tightened		Kedar, Arjun	4.5 hrs	Pending	2-Feb-26

12-Feb-26	DAILY MAINTENANCE REPORT M-tech = Mechanical Technician E-Tech = Auto Electrician L-Tech = Lube W-Tech = Welder							M-Techs: 6	E-Tech: 1	L-Tech: 1	W-Tech: 2
S/N	**Asset Code**	**Description**	**Date of B/D**	**BD Days**	**Location**	**Breakdown Reason**	**Components**	**Technicians**	**Duration**	**Status**	**Maintained**
High Commercial Vehicle (HCV): 4											
1	321 39 86	Eicher- 10 wheeler	6-Feb-26	14	WORKSHOP	Engine assy under maintenance		Arjun, Balmukunda, Kedar, Ram, Alek	6.5 hrs	Pending	-
2	321 39 110	Eicher-10 wheeler	12-Feb-26	8	WORKSHOP	Radiator leakage issue attended & lubricated all joints; Hydraulic pressure pipe defective; attended	Bondtite, Resibond, Grease	Binod, Ajrun	2.5 hrs	Completed	10-Feb-26
3	321 39 128	Lowbed	12-Feb-26	8	WORKSHOP	Tyre puncture issue resolved		Manish, Alek	1.5 hrs	Completed	5-Feb-26
4	321 39 111	Eicher-6 wheeler	12-Feb-26	8	WORKSHOP	Brakes adjusted		Arjun, Alek	1 hr	Completed	10-Feb-26
Hydraulic Excavator (HE): 5											
5	321 45 16	Excavator 360 (Hyundai)	17-Jan-26	34	WORKSHOP	Fuel pump issue persists despite completion of all corrective actions; engagement of a specialized pump repair technician arrived; under maintenance		Pump Tech	1 hr	Pending	9-Jan-26
6	321 45 44	CAT Excavator 323D3	12-Feb-26	8	SHINWA	Bucket replaced and all pins, bushings, and linkages fully lubricated	Repaired bucket,shims Grease	Sagar, Manish	1.5 hrs	Completed	8-Feb-26
7	321 45 19	Komatsu Excavator PC-210	12-Feb-26	8	RIVERBED	Bucket substituted, Teeths replaced and full lubrication executed across all joints and linkage points	Repaired bucket,shims, Teeths,locks & pins, Grease	Sagar, Binod, Kedar	1.5 hrs	Completed	8-Feb-26
8	321 45 38	Komatsu Excavator PC-210	12-Feb-26	8	SURGESHAFT	Repaired battery replaced	Repaired battery	Ram	1 hr	Completed	10-Feb-26
9	321 45 42	CAT Excavator 323D3	12-Feb-26	8	ADIT	Bucket shims replaced	Shims	Sagar, Binod	30 min	Completed	9-Feb-26
Rock Hammer Breaker: 2											
10	-	Breaker hammer	2-Feb-26	18	WORKSHOP	Maintenance completed	N2, Hose,Sleeve fittings	Kedar	3 hrs	Completed	2-Feb-26
11	-	Breaker hammer	12-Feb-26	8	WORKSHOP	Through bolt issue; under maintenance		Kedar	2.5 hrs	Pending	2-Feb-26
Backhoe: 2											
12	321 44 49	Backhoe-JCB	12-Feb-26	8	WORKSHOP	Lubricants applied to all pivot assemblies, linkages, and fittings	Grease	Binod	30 min	Completed	7-Feb-26
13	321 44 40	Backhoe-Bull	12-Feb-26	8	WORKSHOP	All moving joints, pivot points, and fittings received proper lubrication.	Grease	Binod	20 min	Completed	10-Feb-26
Wheel Loader: 1											
14	321 44 52	Wheel Loader-Lonking	12-Feb-26	8	WORKSHOP	Preventive lubrication was applied to all critical pivot assemblies, linkages, and fittings.	Grease	Binod	30 min	Completed	8-Feb-26
Light Commercial Vehicle (LCV): 1											
15	PR101001CH A9311	Scorpio	12-Feb-26	8	WORKSHOP	Suspension bush issue; no stock		Balmukunda, Alek	30 min	Completed	-

13-Feb-26	DAILY MAINTENANCE REPORT M-tech = Mechanical Technician E-Tech = Auto Electrician L-Tech = Lube W-Tech = Welder							M-Techs: 6	E-Tech: 1	L-Tech: 1	W-Tech: 2
S/N	**Asset Code**	**Description**	**Date of B/D**	**BD Days**	**Location**	**Breakdown Reason**	**Components**	**Technicians**	**Duration**	**Status**	**Maintained**
High Commercial Vehicle (HCV): 5											
1	321 39 86	Eicher- 10 wheeler	6-Feb-26	14	WORKSHOP	Engine assy under maintenance		Arjun, Balmukunda, Kedar, Ram, Alek	9 hrs	Pending	-
2	321 39 107	Eicher-10 wheeler	13-Feb-26	7	WORKSHOP	Air filter changed; Crown oil seal bearing issue; under maintenance; Radiator hose mobil leakage issue attended	Filter air element	Arjun, Mandip, Balmukunda	3 hrs	Completed	11-Feb-26
3	321 39 139	Eicher-10 wheeler	13-Feb-26	7	WORKSHOP	Hydraulic boom cylinder raising issue resolved	Salvaged PTO	Balmukunda	1.5 hrs	Completed	9-Feb-26
4	321 39 111	Eicher-6 wheeler	13-Feb-26	7	WORKSHOP	Cabin foot step welded	Electrodes	Raymon	25 min	Completed	12-Feb-26
5	321 39 97	Eicher-10 wheeler	13-Feb-26	7	WORKSHOP	Balance rod bush to be changed initial hours		Mandip	20 min	Completed	5-Feb-26
Hydraulic Excavator (HE): 4											
6	321 45 25	Hyundai Excavator 220LS	24-Dec-25	58	MAT	Track chain dislodged; idler, sprockets, link bushes, and seals replacement required; items received; Under maintenance	Track link,Track nut & bolts, Roller, Sprocket	Sagar, Anil, Binod	9.5 hrs	Pending	22-Dec-25
7	321 45 16	Excavator 360 (Hyundai)	17-Jan-26	34	WORKSHOP	Fuel pump issue persists despite completion of all corrective actions; engagement of a specialized pump repair technician arrived; under maintenance		Pump Tech, Ram	10 hrs	Pending	9-Jan-26
8	321 45 21	Komatsu Excavator PC-210	13-Feb-26	7	Surgeshaft	Rock hammer breaker hose damaged; replaced with repaired one	Repaired breaker hose; sleeve fitting	Kedar	1.5 hrs	Completed	10-Feb-26
9	321 45 43	CAT Excavator 323D3	13-Feb-26	7	CRUSHER	6 Bucket teeths,locks and pins replaced	Bucket teeths, locks pins	Sagar, Anil, Binod	15 min	Completed	3-Feb-26
Rock Hammer Breaker: 2											
10	-	Breaker hammer	12-Feb-26	8	WORKSHOP	Through bolt issue; maintenance completed		Kedar	4 hrs	Completed	2-Feb-26
11	-	Breaker hammer	13-Feb-26	7	WORKSHOP	Housing damaged sent from TK5; under maintenance		Kedar	2.5 hrs	Pending	2-Feb-26
Light Commercial Vehicle (LCV): 2											
12	341 03 38	Mahindra Bolero	13-Feb-26	7	WORKSHOP	Starting issue; relay and battery needs immediate replacement		Ram	2 hrs	Pending	11-Feb-26
13	341 03 43	MAHINDRA BOLERO	13-Feb-26	7	WORKSHOP	Wiring issue attended and resolved		Ram	1 hr	Completed	10-Feb-26
Wheel Loader: 1											
14	321 44 45	Wheel Loader-Lonking	13-Feb-26	7	WORKSHOP	Preventive lubrication was applied to all critical pivot assemblies, linkages, and fittings.	Grease	Mandip	20 min	Completed	8-Feb-26
Tractor: 1											
15	321 38 28	Tractor Arjun- Mahendra	13-Feb-26	7	WORKSHOP	Fuel tank pipe leakage issue resolved; Head seat supports welded and repaired	Electrodes	Raymond, Manish, Mandip, Balmukunda	1.5 hrs	Completed	11-Feb-26

14-Feb-26	DAILY MAINTENANCE REPORT M-tech = Mechanical Technician E-Tech = Auto Electrician L-Tech = Lube W-Tech = Welder						M-Techs: 5	E-Tech: 1	L-Tech: 1	W-Tech: 1
S/N	**Asset Code**	**Description**	**Date of B/D**	**BD Days**	**Location**	**Breakdown Reason**	**Components**	**Technicians**	**Duration**	**Status**	**Maintained**
High Commercial Vehicle (HCV): 5											
1	321 39 86	Eicher- 10 wheeler	6-Feb-26	14	WORKSHOP	Engine overhaul and servicing completed;post-service testing planned for initial hours of operation tomorrow	Piston rings set; Gaskit kit set; bushes; Engine Oil, Engine Oil filter, Fuel filters	Arjun, Balmukunda, Alek, Mandip	10 hrs	Pending	-
2	321 39 97	Eicher-10 wheeler	14-Feb-26	6	WORKSHOP	BREAKDOWN-Balance rod bush; tail pinion issue		Balmukunda, Mandip	30 min	Pending	5-Feb-26
3	321 39 110	Eicher-10 wheeler	14-Feb-26	6	WORKSHOP	BREAKDOWN-Foot brake valve issue; radiator assy leakage issue		Arjun, Manish	30 min	Pending	12-Feb-26
4	321 39 156	TATA BULKER	14-Feb-26	6	WORKSHOP	Brake linings replaced		Balmukunda, Alek; Mandip	1.5 hrs	Completed	6-Jan-26
5	321 39 134	Eicher-10 wheeler	14-Feb-26	6	WORKSHOP	Tyre pressure checked and maintained		Manish, Mandip	40 min	Completed	11-Feb-26
Hydraulic Excavator (HE): 7											
6	321 45 25	Hyundai Excavator 220LS	24-Dec-25	58	MAT	Track chain dislodged; idler, sprockets, link bushes, and seals replacement required; items received; Under maintenance	Track link,Track nut & bolts, Roller, Sprocket	Sagar, Anil, Manish, Binod	9.5 hrs	Completed	22-Dec-25
7	321 45 16	Excavator 360 (Hyundai)	17-Jan-26	34	WORKSHOP	Fuel pump issue persists despite completion of all corrective actions; engagement of a specialized pump repair technician arrived; couldn't fix the issue; fuel pump injector nozzles needs to be resent for repair		Pump Tech, Ram	8.5 hrs	Pending	9-Jan-26
8	321 45 21	Komatsu Excavator PC-210	14-Feb-26	6	ADIT	Preventive lubrication was applied to all critical pivot assemblies, linkages, and fittings.	Grease	Kedar, Binod	15 min	Completed	10-Feb-26
9	321 45 38	Komatsu Excavator PC-210	14-Feb-26	6	ADIT	Bucket teeth lock bolt replaced and fully lubricated	Bolt,Grease	Kedar, Binod	30 min	Completed	10-Feb-26
10	321 45 44	CAT Excavator 323D3	14-Feb-26	2	SHINWA	Bucket entire teeths, locks and pins replaced and greased	Bucket teeths, locks & pins, Grease	Kedar, Binod	1.5 hrs	Completed	12-Feb-26
11	321 45 42	CAT Excavator 323D3	14-Feb-26	2	SHINWA	Bucket pin bolt replaced and greased	Bolt,Grease	Kedar, Binod	1 hr	Completed	12-Feb-26
12	321 45 39	Kobelco Excavator SK220	14-Feb-26	6	ZEROKILO	Comprehensive lubrication of all moving components completed	Grease	Kedar, Binod	15 min	Completed	8-Feb-26
Backhoe: 1											
13	321 44 49	Backhoe-JCB	14-Feb-26	6	WORKSHOP	Lubricants applied to all pivot assemblies, linkages, and fittings	Grease	Binod	30 min	Completed	12-Feb-26

16-Feb-26	DAILY MAINTENANCE REPORT M-tech = Mechanical Technician E-Tech = Auto Electrician L-Tech = Lube W-Tech = Welder						M-Techs: 5	E-Tech: 1	L-Tech: 0	W-Tech: 1
S/N	**Asset Code**	**Description**	**Date of B/D**	**BD Days**	**Location**	**Breakdown Reason**	**Components**	**Technicians**	**Duration**	**Status**	**Maintained**
High Commercial Vehicle (HCV): 6											
1	321 39 86	Eicher- 10 wheeler	6-Feb-26	14	WORKSHOP	Engine overhaul and servicing completed;post-service testing carried out the entire day		Arjun, Balkumunda, Alek	9 hrs	Completed	-
2	321 39 110	Eicher-10 wheeler	14-Feb-26	6	WORKSHOP	Clutch cylinder replaced; Brakes adjusted	Clutch cylinder	Arjun, Mandip	1.5 hrs	Completed	12-Feb-26
3	321 39 93	Eicher-6 wheeler	16-Feb-26	4	WORKSHOP	FR RH LH Cabin foot rest welded, drilled and repaired, RR LH srping bracket replaced; foreign object removed	Spring brkt, screws	Sagar, Anil	3 hrs	Completed	8-Feb-26
4	321 39 111	Eicher-6 wheeler	16-Feb-26	4	WORKSHOP	Tyre puncture replaced	Repaired Tyre	Arjun, Alek	30 min	Completed	13-Feb-26
5	321 39 128	Lowbed	16-Feb-26	4	WORKSHOP	Tyre pressure issue resolved; Fully greased and all suspension nut & bolts tightened	Grease	Mandip, Sagar, Alek	1.5 hrs	Completed	12-Feb-26
6	P03002KHA38	ASHOK LAYLAND-TRUCK	16-Feb-26	4	WORKSHOP	FR RH Door repaired		Anil, Kedar	1 hr	Completed	-
Hydraulic Excavator (HE): 3											
7	321 45 40	CAT Excavator 323D3	16-Feb-26	4	WORKSHOP	Bucket teeths locks and pins replaced	Bucket teeths, pins	Kedar	15 min	Completed	-
8	321 45 21	Komatsu Excavator PC-210	16-Feb-26	4	ADIT	Air filter element replaced; Preventive lubrication was applied to all critical pivot assemblies, linkages, and fittings.	Air cleaner; Grease	Sagar	20 min	Completed	14-Feb-26
9	321 45 42	CAT Excavator 323D3	16-Feb-26	2	SHINWA	Bucket teeths pins & bolts replaced	Lock pins	Kedar	1 hr	Completed	12-Feb-26
Light Commercial Vehicle (LCV): 1											
10	341 03 40	Mahindra Bolero	16-Feb-26	4	WORKSHOP	Uj cross issue resolved; FR RH door lock issue resolved	Yoke & teeth; Uj cross	Arjun, Alek, Ram	3 hrs	Completed	11-Feb-26
Boomer: 1											
11	321 39 127	Epiroc	16-Feb-26	4	WORKSHOP	Electrical ckts wiring issue attended		Ram	1 hr	Completed	-

17-Feb-26			DAILY MAINTENANCE REPORT M-tech = Mechanical Technician | E-Tech = Auto Electrician | L-Tech = Lube | W-Tech = Welder						M-Techs: 6	E-Tech: 1	L-Tech: 1	W-Tech: 1
S/N	Operator	Asset Code	Description	Date of B/D	B/D Days	Location	Breakdown Reason	Components	Technicians	Duration	Status	Maintained
High Commercial Vehicle (HCV): 6												
1		321 39 86	Eicher- 10 wheeler	6-Feb-26	14	WORKSHOP	Engine mountings fitted; Electrical wiring ckts issues attended; FR LH RH door inner handle fabricated		Balkumunda, Alek	4.5 hrs	Completed	-
2	Prithi Rai	321 39 97	Eicher-10 wheeler	14-Feb-26	6	WORKSHOP	Tail pinion assy swapped with salvaged unit from TK-5 acdt vehicle; Horn issue attended ; Balance rod bush replaced; tightening and fittment finalizes tomorrow initial hours	Salvaged tail pinon assy, Grease	Balmukunda, Manish, Sagar, Binod, Ram, Alek	7 hrs	Pending	5-Feb-26
3	Kriti Rai	321 39 139	Eicher-10 wheeler	17-Feb-26	3	WORKSHOP	Punctured tyre repaired and greased	Grease	Binod,Manish	1.5 hrs	Completed	13-Feb-26
4	Bishnu Raj Subba	321 39 111	Eicher-6 wheeler	17-Feb-26	3	WORKSHOP	Fuel injection pump pipe leakage rectified		Arjun, Anil	2 hrs	Completed	16-Feb-26
5	Chandra Bd. Bhujel	321 39 134	Eicher-10 wheeler	17-Feb-26	3	WORKSHOP	Radiator assembly leakage addressed by applying a Bondtite–Resibond compound; left it for curing	Bondtite-resibond	Arjun, Alek	3 hrs	Pending	14-Feb-26
6	Pema Dorje Tamang	321 39 107	Eicher-10 wheeler	17-Feb-26	3	WORKSHOP	Cabin stabilizer bar welded & repaired; head light wiring issue attended	Electrodes, Tyre	Balmukunda, Alek, Arjun, Ram	4 hrs	Completed	13-Feb-26
Hydraulic Excavator (HE): 7												
7	Kumar Basnet	321 45 42	CAT Excavator 323D3	17-Feb-26	3	SHINWA	Bucket under repair finalizes tomorrow; Fully lubricated	Grease	Sagar, Binod	20 min	Completed	14-Feb-26
8	Arjun Mangrati	321 45 25	Hyundai Excavator 220LS	17-Feb-26	3	CRUSHER	Battery terminal, Starting issue resolved and fully lubricated	Grease	Ram, Kedar, Binod	1.5 hrs	Completed	24-Dec-25
9	Mahabir Baniya	321 45 39	Kobelco Excavator SK220	17-Feb-26	3	SHINWA	Rock breaker bolts tightened and greased	Grease	Sagar, Binod	40 min	Completed	14-Feb-26
10	Indra Bd. Shrestha	321 45 29	XCMG Excavator 215C	17-Feb-26	3	THUMBA	Bucket linkage assy damaged; under maintenance	H-Link	Kedar, Manish	5 hrs	Pending	11-Feb-26
11	Pankaj Kr. Yadav	321 45 44	CAT Excavator 323D3	17-Feb-26	3	SHINWA	All moving joints, pivot points, and fittings received proper lubrication.	Grease	Sagar, Binod	20 min	Completed	14-Feb-26
12	Maan Dhoj Tamang	321 45 41	CAT Excavator 323D3	17-Feb-26	3	SHINWA	Lubricants applied to all pivot assemblies, linkages, and fittings	Grease	Sagar, Binod	20 min	Completed	7-Feb-26
13	Basanta Limbu	321 45 51	Kobelco Excavator SK380	17-Feb-26	3	SHINWA	Comprehensive lubrication of all moving components completed	Grease	Sagar, Binod	20 min	Completed	-
Light Commercial Vehicle (LCV): 2												
14	Milan Bhujel	341 03 40	Mahindra Bolero	16-Feb-26	4	WORKSHOP	Propeller shaft repaired; Greased and tyre repaired	Electrodes, Tyre	Alek, Anil, Manish	3 hrs	Completed	11-Feb-26
15	Jiban Bhujel	LUPR01001CHA3504	Mahindra Bolero	17-Feb-26	3	WORKSHOP	Tyres replaced	Tyre	Manish	15 min	Completed	5-Feb-26
Boomer: 1												
16	Subash Shrestha	321 39 127	Epiroc	17-Feb-26	3	WORKSHOP	Manuplulator rotation switch issue resolved		Ram	45 min	Completed	16-Feb-26

DAILY MAINTENANCE REPORT

18-Feb-26

M-tech = Mechanical Technician | E-Tech = Auto Electrician | L-Tech = Lube | W-Tech = Welder

M-Techs: 7 | E-Tech: 1 | L-Tech: 1 | W-Tech: 1

S/N	Operator	Asset Code	Description	Date of B/D	B/D Days	Location	Breakdown Reason	Components	Technicians	Duration	Status	Maintained
High Commercial Vehicle (HCV): 6												
1		321 39 86	Eicher- 10 wheeler	6-Feb-26	14	WORKSHOP	Silencer pipe assy fittment issue resolved; FR LH DR glass fabricated and installed	Optical fibre	Balkumunda, Alek, Manish	3.5 hrs	Completed	-
2	Prithi Rai	321 39 97	Eicher-10 wheeler	14-Feb-26	6	WORKSHOP	Tail pinion assy swapped with salvaged unit from TK-5 acdt vehicle; Horn issue attended ; Balance rod bush replaced; tightening and fittment finalized and greased; Gear oil leakage issue attended	Grease	Alek, Arjun	4.5 hrs	Completed	5-Feb-26
3	Chandra Bd. Bhujel	321 39 134	Eicher-10 wheeler	17-Feb-26	3	WORKSHOP	Radiator assembly leakage addressed; Hub bearing issue, tyre pressure issues resolved and fully lubricated	Hub bearing, oil seal, grease, gear oil, grease	Arjun, Mandip, Manish	8 hrs	Completed	14-Feb-26
4	Kriti Rai	321 39 139	Eicher-10 wheeler	18-Feb-26	2	WORKSHOP	Gear shifter lock issue resolved	Salvaged lock	Balmukunda, Alek	30 min	Completed	17-Feb-26
5	Bishnu Raj Subba	321 39 111	Eicher-6 wheeler	18-Feb-26	2	WORKSHOP	Auto slack adjusters issue resolved		Alek, Manish, Arjun	1 hr	Completed	17-Feb-26
6	Buddhiram Chaudhary	321 39 110	Eicher-10 wheeler	18-Feb-26	2	WORKSHOP	FR looking mirror frame issue resolved	Electrodes	Anil, Manish	45 min	Completed	14-Feb-26
Hydraulic Excavator (HE): 6												
7	Kumar Basnet	321 45 42	CAT Excavator 323D3	17-Feb-26	3	SHINWA	Bucket mounted and secured	Repaired bucket	Kedar, Sagar	1 hr	Completed	14-Feb-26
8	Suman Limbu	321 45 40	CAT Excavator 323D3	18-Feb-26	2	WORKSHOP	All moving joints, pivot points, and fittings received proper lubrication.	Grease	Binod	30 min	Completed	16-Feb-26
9	Indra Bd. Shrestha	321 45 29	XCMG Excavator 215C	17-Feb-26	3	THUMBA	Bucket linkage assy damaged; under maintenance	H-Link	Kedar, Manish, Binod	1 hr	Completed	11-Feb-26
10	Sunil Chaulagain	321 45 25	Hyundai Excavator 220LS	18-Feb-26	2	ADIT	Bucket teeths, locks & pins replaced	Bucket teeths, locks & pins and fully lubricated	Sagar	1 hr	Completed	24-Dec-25
11	Birkharaj Tamang	321 45 21	Komatsu Excavator PC-210	18-Feb-26	2	ADIT	Preventive lubrication was applied to all critical pivot assemblies, linkages, and fittings.	Grease	Sagar	15 min	Completed	14-Feb-26
12	Dipendra Sunuwar	321 45 38	Komatsu Excavator PC-210	18-Feb-26	2	ADIT	All articulated joints, linkages, and fittings were lubricated as per standard practice.	Grease	Sagar	20 min	Completed	14-Feb-26
Light Commercial Vehicle (LCV): 1												
13		BA19CHA6047	Toyota- Hilux	18-Feb-26	2	WORKSHOP	Rear suspension noise issue attended		Balmukunda	2 hrs	Completed	-
Backhoe: 1												
14	Rajan Chaudhary	321 44 40	Backhoe-Bull	18-Feb-26	2	WORKSHOP	All moving joints, pivot points, and fittings received proper lubrication.	Grease	Binod	20 min	Completed	12-Feb-26
Transit Mixture: 1												
15	Rajendra Bhujel	321 39 151	TATA Putzmeister Mixture	18-Feb-26	2	WORKSHOP	Water pump v ribbed belt replaced	V belt	Balmukunda, Alek	1 hr	Completed	27-Jan-26
Rock Breaker Hammer: 1												
16	-	-	Breaker hammer	13-Feb-26	7	WORKSHOP	Housing damaged sent from TK5; under maintenance		Kedar	3 hrs	Pending	2-Feb-26

19-Feb-26			DAILY MAINTENANCE REPORT M-tech = Mechanical Technician | E-Tech = Auto Electrician | L-Tech = Lube | W-Tech = Welder						M-Techs: 6	E-Tech: 1	L-Tech: 1	W-Tech: 2
S/N	Operator	Asset Code	Description	Date of B/D	B/D Days	Location	Breakdown Reason	Components	Technicians	Duration	Status	Maintained
High Commercial Vehicle (HCV): 4												
1	**Prithi Rai**	321 39 97	Eicher-10 wheeler	14-Feb-26	6	WORKSHOP	Gear oil leakage issue resolved; tail pinionoil seal replaced	Oil seal, Gear Oil	Arjun, Manish	1.5 hrs	Completed	5-Feb-26
2	**Buddhiram Chaudhary**	321 39 110	Eicher-10 wheeler	19-Feb-26	1	WORKSHOP	Rear buggy shiftment issue attended		Alek, Balmukunda	45 min	Completed	18-Feb-26
3	**Rajendra Bhujel**	321 39 154	TATA BULKER	19-Feb-26	1	WORKSHOP	Cetnre bolts issue; tightenend and issue resolved		Arjun, Manish	30 min	Completed	-
4		PRA101001KHA4512	ASHOK LEYLAND	19-Feb-26	1	WORKSHOP	Propeller shaft nuts and bolts tightened		Manish	30 min	Completed	-
Hydraulic Excavator (HE): 1												
5	**Sunil Chaulagain**	321 45 38	Komatsu Excavator PC-210	19-Feb-26	1	SURGESHAFT	Bucket link defect repaired, shims replaced	Shims	Sagar, Anil	3 hrs	Completed	18-Feb-26
Light Commercial Vehicle (LCV): 2												
6	**Som Tamang**	PR301024CHA9018	Toyota hilux	19-Feb-26	1	WORKSHOP	Brake shoe replaced	Brake shoe	Sagar, Binod	1 hr	Completed	5-Feb-26
7	**Milan Bhujel**	341 03 40	Mahindra Bolero	19-Feb-26	1	WORKSHOP	Crown Wheel & Pinion Set issue		Arjun, Manish	1.5 hrs	Completed	16-Feb-26
Rock Hammer Breaker: 1												
8	-	-	Breaker hammer	13-Feb-26	7	WORKSHOP	Color bush to be replaced; housing under repair	Color bush, Inner bush	Kedar	3 hrs	Pending	2-Feb-26
Tractor: 1												
9	**Milan Gurung**	321 38 35	Tractor Arjun- Mahendra	19-Feb-26	1	WORKSHOP	Hydraulic Pipe fittings issue resolved		Manish	15 min	Completed	11-Feb-26
Transit Mixture: 1												
10	-	320 39 108	T.M. CONMAT	19-Feb-26	1	WORKSHOP	Hopper bearings replaced	Bearings	Alek	2 hrs	Completed	16-Jan-26
Boomer: 1												
11	**Subash Shrestha**	321 39 126	Epiroc	19-Feb-26	1	WORKSHOP	Motor housing switch repaired		Ram	2 hrs	Completed	-

20-Feb-26			DAILY MAINTENANCE REPORT M-tech = Mechanical Technician | E-Tech = Auto Electrician | L-Tech = Lube | W-Tech = Welder						M-Techs: 6	E-Tech: 1	L-Tech: 1	W-Tech: 3
S/N	Operator	Asset Code	Description	Date of B/D	B/D Days	Location	Breakdown Reason	Components	Technicians	Duration	Status	Maintained
High Commercial Vehicle (HCV): 1												
1	Chandra Bd. Bhujel	321 39 134	Eicher-10 wheeler	20-Feb-26	2	WORKSHOP	Rear buggy body panel damage rectified by replacing old unit by repairing and welding; Self assy repaired and fitted; Tyre puncture repaired and replaced at THAUWA		Anil, Bhim, Sagar Ram, Manish, Arjun	6 hrs	Completed	17-Feb-26
Hydraulic Excavator (HE): 3												
2	Suman Limbu	321 45 40	CAT Excavator 323D3	20-Feb-26	2	WORKSHOP	All moving joints, pivot points, and fittings received proper lubrication.	Grease	Binod	15 min	Completed	18-Feb-26
3	Kumar Basnet	321 45 42	CAT Excavator 323D3	20-Feb-26	2	SHINWA	Repaired bucket replaced and greased	Repaired bucket, Grease	Kedar, Binod	1.5 hrs	Completed	17-Feb-26
4	Sunil Chaulagain	321 45 25	Hyundai Excavator 220LS	20-Feb-26	2	SURGESHAFT	Starting issue; dynamo regulator damaged, needs to be sent for repair		Ram, Sagar	2 hrs	Completed	18-Feb-26
Light Commercial Vehicle (LCV): 2												
5	Ankaman Rai	341 03 38	Mahindra Bolero	20-Feb-26	2	WORKSHOP	Starting issue; battery REPLACED ; relay NEEDS immediate replacement; Jhula washer, pins replaced, Engine mounting RR welded and repaired, Uj cross changed	Battery, Washer & pins, Jhula, Electrodes, Uj cross	Arjun, Alek, Bhim	3.5 hrs	Completed	11-Feb-26
6	Sanil Bhujel	341 03 43	Mahindra Bolero	20-Feb-26	2	WORKSHOP	Punctured tyre repaired		Alek	1 hr	Completed	13-Feb-26
Rock Hammer Breaker: 1												
7	-	-	Breaker hammer	13-Feb-26	9	WORKSHOP	Color bush to be replaced; housing under repair	Color bush, Inner bush	Kedar, Bhim	3 hrs	Pending	2-Feb-26
Shotcrete Machine: 1												
8	Nabin Balami	321 39 109	Shotcrete M/C-Robot	19-Feb-26	3	WORKSHOP	Slew drive, Dust seals, Victaulic style couplings, hopper side foreign objects removal, boom cylinder seals, check nut fabrication; all under maintannce	Grease	Bahmukunda, Ajjesh, Kedar, Sagar, Binod	5.5 hrs	Pending	-

DAILY MAINTENANCE REPORT

21-Feb-26	M-tech = Mechanical Technician | E-Tech = Auto Electrician | L-Tech = Lube | W-Tech = Welder	M-Techs: 6	E-Tech: 1	L-Tech: 1	W-Tech: 3

S/N	Operator	Asset Code	Description	Date of B/D	B/D Days	Location	Breakdown Reason	Components	Technicians	Duration	Status	Maintained
High Commercial Vehicle (HCV): 7												
1	**Prithi Rai**	321 39 97	Eicher-10 wheeler	21-Feb-26	0	WORKSHOP	Engine oil top up	Engine oil	Arjun	20 min	Completed	14-Feb-26
2	**Bishnu Raj Subba**	321 39 111	Eicher-6 wheeler	21-Feb-26	0	WORKSHOP	Tyre puncture issue resolved, Brakes adjusted	Tyre	Arjun, Manish, Alek	1.5 hrs	Completed	18-Feb-26
3	**Buddhiram Chaudhary**	321 39 110	Eicher-10 wheeler	21-Feb-26	0	WORKSHOP	Rear buggy shiftment issue attended		Alek, Balmukunda	45 min	Completed	19-Feb-26
4	**Pema Dorje Tamang**	321 39 107	Eicher-10 wheeler	21-Feb-26	0	WORKSHOP	Hoist Cylinder Mounting Bracket cracked parts welded and repaired	Electrodes	Reman, Anil	1.5 hrs	Completed	17-Feb-26
5	-	321 39 140	TATA Lowbed	21-Feb-26	0	WORKSHOP	Rear buggy parts welded and repaired; Head lamp issue rectified	Electrodes	Anil, Bhim, Ram	1.5 hrs	Completed	-
6	**Chandra Bd. Bhujel**	321 39 134	Eicher-10 wheeler	21-Feb-26	0	WORKSHOP	Tyre replaced; Self assy tried repairing, all carbon from 1 unit & bendix drive of another unit found defective ; used of poor quality by the repairing shop,under maintenance	2 Repaired Startor Assy	Ram	3 hrs	Pending	20-Feb-26
7	**Mithun Chaudhary**	321 39 125	Mini Truck SML (4 Wheeler)	21-Feb-26	0	WORKSHOP	Leafsprings to be added	Leaf springs	Sagar	1 hr	Pending	9-Feb-26
Hydraulic Excavator (HE): 2												
8	**Indra Bd. Shrestha**	321 45 29	XCMG Excavator 215C	21-Feb-26	0	THUMBA	Teeths locks and pins replaced and greased	Teeths locks & pins, Grease	Sagar, Binod	45 min	Completed	17-Feb-26
9	**Kumar Basnet**	321 45 42	CAT Excavator 323D3	21-Feb-26	0	SHINWA	Bucket teeths locks & pins replaced	Locks & pins	Kedar	25 min	Completed	20-Feb-26
Light Commercial Vehicle (LCV): 3												
10	**Ankaman Rai**	341 03 38	Mahindra Bolero	20-Feb-26	1	WORKSHOP	Crown oil pinion seal FR RR replaced, gear oil & steering oil top up, Engine mounting replaced	Oil seal, mounting, Gear oil, steering oil	Arjun, Manish, Alek	3.5 hrs	Completed	11-Feb-26
11	**Sanil Bhujel**	341 03 43	Mahindra Bolero	21-Feb-26	0	WORKSHOP	Brakes adjusted, RR brakes maintained, brake oil top up	Brake oil	Arjun	1 hr	Completed	20-Feb-26
12	**Jiban Bhujel**	LUPR01001CHA3504	Mahindra Bolero	21-Feb-26	0	WORKSHOP	RR tail light electrical ckts issue resolved		Ram	1 hr	Completed	17-Feb-26
Rock Hammer Breaker: 1												
13	-	-	Breaker hammer	13-Feb-26	8	WORKSHOP	Color bush to be replaced; housing under repair	Color bush, Inner bush	Kedar, Bhim	3 hrs	Pending	2-Feb-26
Shotcrete Machine: 1												
14	**Nabin Balami**	321 39 109	Shotcrete M/C-Robot	19-Feb-26	2	WORKSHOP	Check nut fitted, Hopper assy maintenance completed	Fabricated check nut	Balmukunda, Anil, Alek, Ram	7 hrs	Completed	-
D.G.: 1												
15	-	321 07 59	Jackson CJ125DSP 125KVA	21-Feb-26	0	WORKSHOP	Full preventive maintenance carried out.	Engine oil, Oil filter, Fuel filters	Sagar, Binod	2 hrs	Completed	-
Air Compressor.: 1												
16	-	321 03 68	Diesel Air Compressor XAS 400-100	21-Feb-26	0	WORKSHOP	Engine rubber buffers to be replaced	Rubber buffer engine	Kedar, Manish, Arjun	1.5 hrs	Pending	-
Tractor: 1												
17	**Shyam Chaudhary**	321 38 28	Tractor Arjun- Mahendra	21-Feb-26	0	WORKSHOP	Battery replaced	Battery	Ram	45 min	Completed	13-Feb-26
Boomer: 1												
18	**Subash Shrestha**	321 39 126	Epiroc	21-Feb-26	0	WORKSHOP	Tyre puncture issue; replaced from 39 127		Arjun, Alek, Manish, Sagar	2 hrs	Completed	19-Feb-26

22-Feb-26			DAILY MAINTENANCE REPORT M-tech = Mechanical Technician | E-Tech = Auto Electrician | L-Tech = Lube | W-Tech = Welder								M-Techs: 5 E-Tech: 1 L-Tech: 1 W-Tech: 3		
S/N	Operator	Asset Code	Description	Date of B/D	B/D Days	Location	Breakdown Reason	Components	Technicians	Duration	Repair Status	Operational Status	Maintained
High Commercial Vehicle (HCV): 5													
1	Chandra Bd. Bhujel	321 39 134	Eicher-10 wheeler	21-Feb-26	2	WORKSHOP	Tyre replaced; Self assy tried repairing, all carbon from 1 unit & bendix drive of another unit found defective ; used of poor quality by the repairing shop,under maintenance	2 Repaired Startor Assy	Ram	3 hrs	Completed	ACTIVE	20-Feb-26
2	Mithun Chaudhary	321 39 125	Mini Truck SML (4 Wheeler)	21-Feb-26	2	WORKSHOP	FR LH 3 Leaf springsadded	Leaf springs	Sagar, Manish	3.5 hrs	Completed	ACTIVE	9-Feb-26
3	Kiroj Chaudhary	321 39 112	Eicher-6 wheeler	22-Feb-26	1	WORKSHOP	Start key issue, Pump solenoid issue attended and resolved, filter choke issue resolved		Arjun, Sagar, Balmukunda, Ram	2 hrs	Completed	ACTIVE	20-Feb-26
4	Ganesh Bhattarai	321 39 142	Lowbed	22-Feb-26	1	WORKSHOP	All moving joints, pivot points, and fittings received proper lubrication.	Grease	Binod	30 min	Completed	ACTIVE	26-Jan-26
5		PRNO203001 KA1163	Tata - Prima	22-Feb-26	1	WORKSHOP	RR RH leaf springs issue; under maintenance		Binod, Sagar	1.5 hrs	Pending	BREAKDOWN	-
Shotcrete Machine: 1													
6	Nabin Balami	321 39 109	Shotcrete M/C-Robot	19-Feb-26	4	WORKSHOP	All maintenance completed; FR lamp frame frabricated and welded	Electrodes	Balmukunda, Anil, Alek, Ram	3.5 hrs	Completed	ACTIVE	-
Rock Hammer Breaker: 1													
7	-	-	Breaker hammer	13-Feb-26	10	WORKSHOP	Color bush to be replaced; housing under repair	Electrodes	Kedar, Reman	6 hrs	Pending	BREAKDOWN	2-Feb-26
Air Compressor.: 1													
8	-	321 03 68	Diesel Air Compressor XAS 400-100	21-Feb-26	2	WORKSHOP	Engine rubber buffers, new battery replaced and complete maintenance completed	Rubber buffers engine, Engine oil, Engine oil filter, Diesel filter, Air filter, Battery	Kedar, Arjun, Ram, Balmukunda	7 hrs	Completed	ACTIVE	-
Wheel Loader: 1													
9	Hari Narayan	321 44 45	Wheel Loader-Lonking	22-Feb-26	1	WORKSHOP	Air filter choke issue; parts already ordered not received yet;Coolant replenished by 5L, Hydraulic pipe leakage issue attended	Coolant, Bondtitie	Manish, Sagar	3 hrs	Completed	ACTIVE	13-Feb-26
Boomer: 1													
10	Subash Shrestha	321 39 127	Epiroc	22-Feb-26	1	WORKSHOP	Tyre under maintenance; Tube to be replaced, placed order PR No:780		Arjun, Alek, Manish, Sagar, Balmukunda	1 hr	Pending	BREAKDOWN	19-Feb-26
Transit Mixture: 1													
11	Purna B.K.	321 39 145	TATA putzmeister Mixture	22-Feb-26	1	WORKSHOP	Hardened concrete deposits within the hopper were mechanically removed, Hopper nut & bolts tightened, Auto race, solenoid issue attended and lubricated	Grease	Balmukunda, Arjun, Manish, Ram, Binod	3.5 hrs	Completed	ACTIVE	6-Feb-26
Tractor: 1													
12	Raj Tamang		Hired- John Deere	22-Feb-26	1	WORKSHOP	Engine oil changed, Blts bolts welded and repaired	Engine oil, Electrodes	Balmukunda, Binod, Bhim	1.5 hrs	Completed	ACTIVE	-

DAILY MAINTENANCE REPORT

23-Feb-26

M-tech = Mechanical Technician | E-Tech = Auto Electrician | L-Tech = Lube | W-Tech = Welder

M-Techs: 5 E-Tech: 1 L-Tech: 1 W-Tech: 3

S/N	Operator	Asset Code	Description	Date of B/D	B/D Days	Location	Breakdown Reason	Components	Technicians	Duration	Repair Status	Operational Status	Maintained
High Commercial Vehicle (HCV): 4													
1	**Birju Shah**	PRNO203001 KA1163	Tata - Prima	22-Feb-26	2	WORKSHOP	RR RH 5 leaf springs issue; under maintenance		Binod, Sagar, Manish, Alek	2 hrs	Completed	**ACTIVE**	-
2	**Buddhiram Chaudhary**	321 39 110	Eicher-10 wheeler	23-Feb-26	1	WORKSHOP	Cabin foot rest welded and repaired and greased; RR pneumatic pipe leakage issue resolved	Electrodes, Grease,Bondtite	Alek, Bhim, Binod, Sagar	2.5 hrs	Completed	**ACTIVE**	21-Feb-26
3	**Pema Dorje Tamang**	321 39 107	Eicher-10 wheeler	23-Feb-26	1	WORKSHOP	Removal of entrapped foreign debris carried out.		Arjun	25 min	Completed	**ACTIVE**	21-Feb-26
4	**Bishnu Raj Subba**	321 39 111	Eicher-6 wheeler	23-Feb-26	1	WORKSHOP	Brakes adjusted		Arjun	15 min	Completed	**ACTIVE**	21-Feb-26
Shotcrete Machine: 1													
5	**Nabin Balami**	321 39 109	Shotcrete M/C-Robot	23-Feb-26	1	WORKSHOP	Hydraulic hose sleeve fittings replaced; Chemical tank assy leakage issue resolved	Sleeve fittings and hose,Electrodes	Balmukunda, Ram	5 hrs	Completed	**ACTIVE**	19-Feb-26
Air Compressor.: 1													
6	-	321 03 68	Diesel Air Compressor XAS 400-100	21-Feb-26	3	WORKSHOP	Supporting bkts welded and repaired	Electrodes	Bhim, Ram, Reman	2 hrs	Completed	**ACTIVE**	-
Tractor: 1													
7	**Raj Tamang**		Hired- John Deere	23-Feb-26	1	WORKSHOP	Cabin supports welded and repaired and comprehensive lubrication carried out	Electrodes, Grease	Reman, Binod	1 hr	Completed	**ACTIVE**	22-Feb-26
Backhoe: 1													
8	**Rajan Chaudhary**	321 44 40	Backhoe-Bull	23-Feb-26	1	WORKSHOP	All moving joints, pivot points, and fittings received proper lubrication.	Grease	Binod	20 min	Completed	**ACTIVE**	18-Feb-26
Transit Mixture: 1													
9	**Purna B.K.**	321 39 90	TRANSIT MIXTURE STETTER	23-Feb-26	1	WORKSHOP	Battery replaced; Servicing items to replace	Salvaged battery	Balmukunda, Ram	1 hr	Completed	**ACTIVE**	6-Feb-26
10	**Narayan B.K.**	321 39 152	TATA putzmeister Mixture	23-Feb-26	1	WORKSHOP	Complete lubrication of all moving assemblies carried out.	Grease	Binod	30 min	Completed	**ACTIVE**	26-Jan-26
Light Commercial Vehicle (LCV): 3													
11	**Ankaman Rai**	341 03 38	Mahindra Bolero	23-Feb-26	1	WORKSHOP	Diesel filter issue, hub bearing and hub flange issue attended; Diesel filter to be replaced tomorrow initial hours		Sagar, Binod	1.5 hrs	Completed	**BREAKDOWN**	20-Feb-26
12	**Jiban Bhujel**	LUPR01001C HA3504	Mahindra Bolero	23-Feb-26	1	WORKSHOP	Suspension bush replaced, parts bolts nuts tightened	Bush	Sagar, Alek, Manish	1 hr	Completed	**ACTIVE**	21-Feb-26
Rock Hammer Breaker: 1													
13	-	-	Breaker hammer	13-Feb-26	11	WORKSHOP	Under Maintenance; Finalizing tomorrow		Kedar, Arjun, Ram	month	Pending	**BREAKDOWN**	2-Feb-26
Hydraulic Excavator (HE): 5													
14	**Suman Limbu**	321 45 40	CAT Excavator 323D3	23-Feb-26	1	MAT	RH Top roller found defective; replaced and fully lubricated	Salvaged Roller, Grease	Kedar, Arjun	2 hrs	Completed	**ACTIVE**	20-Feb-26
15	**Dipendra Sunuwar**	321 45 21	Komatsu Excavator PC-210	23-Feb-26	1	SHINWA	Track chain dislogged issue resolved;Preventive lubrication was applied to all critical pivot assemblies, linkages, and fittings.	Grease	Kedar, Arjun	1 hr	Completed	**ACTIVE**	18-Feb-26
16	**Rajendra Chettri**	321 45 19	Komatsu Excavator PC-210	23-Feb-26	1	SHINWA	Comprehensive lubrication of all moving components completed	Grease	Kedar, Arjun	15 min	Completed	**ACTIVE**	12-Feb-26
17	**Kumar Basnet**	321 45 42	CAT Excavator 323D3	23-Feb-26	1	SHINWA	Full preventive maintenance and comprehensive lubrication performed.	Engine oil, Engine oil filter, Fuel filters, Air Filters, Hydraulic oil, Grease	Alek, Manish	2 hrs	Completed	**ACTIVE**	21-Feb-26
18	**Pankaj Kr. Yadav**	321 45 44	CAT Excavator 323D3	23-Feb-26	1	SHINWA	End-to-end servicing with thorough greasing of all moving components completed.	Engine oil, Engine oil filter, Fuel filters, Air Filters, Hydraulic oil, Grease	Alek, Manish	2 hrs	Completed	**ACTIVE**	17-Feb-26

24-Feb-26	DAILY MAINTENANCE REPORT										M-Techs: 5 E-Tech: 1 L-Tech: 1 W-Tech: 3		
	M-tech = Mechanical Technician | E-Tech = Auto Electrician | L-Tech = Lube | W-Tech = Welder												
S/N	Operator	Asset Code	Description	Date of B/D	B/D Days	Location	Breakdown Reason	Components	Technicians	Duration	Repair Status	Operational Status	Maintained
High Commercial Vehicle (HCV): 4													
1	Pema Dorje Tamang	321 39 107	Eicher-10 wheeler	24-Feb-26	0	WORKSHOP	Air cleaner element cleaned, hub bolts tightenend		Arjun	40 min	Completed	ACTIVE	23-Feb-26
2	Bishnu Raj Subba	321 39 111	Eicher-6 wheeler	24-Feb-26	0	WORKSHOP	Fuel injection pump pipe issue resolved using makeshift solution	Electrodes	Arjun, Kedar, Bhim	2.5 hrs	Completed	ACTIVE	23-Feb-26
3	Kriti Rai	321 39 139	Eicher-10 wheeler	24-Feb-26	0	WORKSHOP	Ignition key , Self assy issue; needs to be replaced asap		Ram	45 min	Completed	BREAKDOWN	18-Feb-26
4	Mithun Chaudhary	321 39 125	Mini Truck SML (4 Wheeler)	24-Feb-26	0	WORKSHOP	4 - wheel drive issue; under maintenance		Balmukunda, Kedar, Sagar	1 hr	Pending	BREAKDOWN	18-Feb-26
Light Commercial Vehicle (LCV): 2													
5	Sanil Bhujel	341 03 43	Mahindra Bolero	24-Feb-26	0	TAWA	Shifted to workshop; Brake pipe issue; Brakes adjusted, FR brakes pad maintained, brake oil top up	Brake pad, Brake oil	Sagar, Manish	2.5 ht	Completed	ACTIVE	21-Feb-26
6		BA16CHA8487	SUMO	24-Feb-26	0	WORKSHOP	Tyre pressure checked		Sagar	10 min	Completed	ACTIVE	-
Hydraulic Excavator (HE): 7													
7	Suman Limbu	321 45 40	CAT Excavator 323D3	24-Feb-26	0	MAT	Comprehensive end-to-end servicing executed, including complete lubrication of all dynamic and load-bearing components.	Engine oil, Engine oil filter, Fuel filters, Air Filters, Hydraulic oil, Grease	Alek, Manish, Binod	1.5 hrs	Completed	ACTIVE	20-Feb-26
8	Dipendra Sunuwar	321 45 43	CAT Excavator 323D3	24-Feb-26	0	CRUSHER	Total system servicing completed, ensuring proper lubrication of all moving assemblies and mechanical linkages.	Engine oil, Engine oil filter, Fuel filters, Air Filters, Hydraulic oil, Grease	Alek, Manish, Binod	1.5 hrs	Completed	ACTIVE	13-Feb-26
9	Kumar Basnet	321 45 44	CAT Excavator 323D3	24-Feb-26	0	SHINWA	Starting issue; emergency swtich issue resolved		Ram	1 hr	Completed	ACTIVE	23-Feb-26
10	Mahabir Baniya	321 45 39	Kobelco Excavator SK220	24-Feb-26	0	TAWA	All articulated joints, linkages, and fittings were lubricated as per standard practice.	Grease	Binod	15 min	Completed	ACTIVE	17-Feb-26
11	Sunil Chaulagain	321 45 42	CAT Excavator 323D3	24-Feb-26	0	SHINWA	Full preventive maintenance and comprehensive lubrication performed.	Grease	Binod	15 min	Completed	ACTIVE	23-Feb-26
12	Basanta Limbu	321 45 51	Kobelco Excavator SK380	24-Feb-26	0	SHINWA	Thorough greasing of all mechanical components successfully completed.	Grease	Binod	15 min	Completed	ACTIVE	17-Feb-26
13	Tara Majhi	321 45 41	CAT Excavator 323D3	24-Feb-26	0	SHINWA	Full-cycle maintenance intervention performed with detailed greasing of all rotating and articulating parts.	Grease	Alek, Manish, Binod	1.5 hrs	Completed	ACTIVE	17-Feb-26
Mobile Crane: 1													
14	-	321 43 18	Truck Mount Crane(Zoomlin) 5tons	24-Feb-26	0	WORKSHOP	Crane rear bogie platform structurally repaired and reinforcement welding completed.	Electrodes	Sagar, Anil, Bhim	1 hr	Completed	ACTIVE	23-Jan-26
Wheel Loader: 1													
15	-	321 44 55	Lonking Wheel Loader	24-Feb-26	0	WORKSHOP	Normal check up complete	Grease	Balmukunda, Binod	20 min	Completed	ACTIVE	-

25-Feb-26			DAILY MAINTENANCE REPORT M-tech = Mechanical Technician | E-Tech = Auto Electrician | L-Tech = Lube | W-Tech = Welder								M-Techs: 5	E-Tech: 1	L-Tech: 1	W-Tech: 3
S/N	Operator	Asset Code	Description	Date of B/D	B/D Days	Location	Breakdown Reason	Components	Technicians	Duration	Repair Status	Operational Status	Maintained	
High Commercial Vehicle (HCV): 5														
1	Mithun Chaudhary	321 39 125	Mini Truck SML (4 Wheeler)	24-Feb-26	1	WORKSHOP	4 - wheel drive issue; maintenance completed	Gear oil	Balmukunda, Alek	2.5 hrs	Completed	ACTIVE	18-Feb-26	
2	Kriti Rai	321 39 86	Eicher- 10 wheeler	25-Feb-26	0	WORKSHOP	Salvaged diaphragm replaced, Head light RH changed,Looking mirror replaced, Starting issue attended, Radiator leakage rectified	Salvaged Diaphragm, Bondtite	Manish, Arjun, Ram, Alek	4.5 hrs	Completed	ACTIVE	17-Feb-26	
3	Pema Dorje Tamang	321 39 107	Eicher-10 wheeler	25-Feb-26	0	WORKSHOP	Inner ball joint issue, brakes adjusted		Manish	2.5 hrs	Completed	ACTIVE	24-Feb-26	
4	Bishnu Raj Subba	321 39 111	Eicher-6 wheeler	25-Feb-26	0	WORKSHOP	Re- Fuel injection pump pipe issue; waiting for parts arrival		Arjun	15 min	Pending	BREAKDOWN	24-Feb-26	
5	Buddhiram Chaudhary	321 39 110	Eicher-10 wheeler	25-Feb-26	0	WORKSHOP	Hydraulic Top up	Hydraulic oil	Manish	30 min	Completed	ACTIVE	23-Feb-26	
Light Commercial Vehicle (LCV): 3														
6		PR101002CH A0362	Mahindra Bolero	25-Feb-26	0	WORKSHOP	Cabin inside Structure welded & repaired, Comprehensive lubrication of all moving components completed	Electrodes, Grease	Binod, Reman	2 hrs	Completed	ACTIVE	21-Feb-26	
7		341 03 30	Mahindra Bolero	25-Feb-26	0	WORKSHOP	Self assy issuel under maintenance	Reparied self	Ram, Balmukunda	3.5 hrs	Pending	BREAKDOWN	-	
8	Ankaman Rai	341 03 38	Mahindra Bolero	25-Feb-26	0	WORKSHOP	Coolant topped up	Coolant	Sagar	15 min	Completed	ACTIVE	23-Feb-26	
Hydraulic Excavator (HE): 5														
9	Milan Begha Lmibu	321 45 40	CAT Excavator 323D3	25-Feb-26	0	MAT	Coolant replenished by 5L, under panel cover issue resolved	Coolant	Kedar, Sagar	1 hr	Completed	ACTIVE	24-Feb-26	
10	Dipendra Sunuwar	321 45 43	CAT Excavator 323D3	25-Feb-26	0	CRUSHER	Air cleaner assy cleaned, Teeth locks pinsfitted	Teeths locks & pins	Kedar, Sagar	20 min	Completed	ACTIVE	24-Feb-26	
11	Birkha Raj Tamang	321 45 42	CAT Excavator 323D3	25-Feb-26	0	SHINWA	Repaired bucket replaced	Repaired bucket	Kedar, Sagar	1.5 hrs	Completed	ACTIVE	23-Feb-26	
12	Indra Bd. Shrestha	321 45 29	XCMG Excavator 215C	25-Feb-26	0	WORKSHOP	Bucket cylinder damaged; Under Maintenance		Kedar, Arjun, Alek	2.5 hrs	Pending	BREAKDOWN	21-Feb-26	
13	Kumar Basnet	321 45 44	CAT Excavator 323D3	25-Feb-26	0	SHINWA	Repaired bucket, shims replaced and greased	Repaired bucket, Shims, Grease	Sagar, Binod	1 hr	Completed	ACTIVE	24-Feb-26	
Transit Mixture: 1														
14	Anil Bhujel	321 39 151	TATA Putzmeister Mixture	25-Feb-26	0	WORKSHOP	Full lubrication of pivot assemblies, linkages, and grease points completed.	Grease	Binod	20 min	Completed	ACTIVE	18-Feb-26	

26-Feb-26			DAILY MAINTENANCE REPORT M-tech = Mechanical Technician | E-Tech = Auto Electrician | L-Tech = Lube | W-Tech = Welder								M-Techs: 5	E-Tech: 1	L-Tech: 1	W-Tech: 3
S/N	Operator	Asset Code	Description	Date of B/D	B/D Days	Location	Breakdown Reason	Components	Technicians	Duration	Repair Status	Operational Status	Maintained	
High Commercial Vehicle (HCV): 3														
1	**Kriti Rai**	321 39 86	Eicher- 10 wheeler	26-Feb-26	10	WORKSHOP	Gear lever locks tightened, maintenance completed; Horn assy needs replacement, 4 wheel drive issue attended	Distribution valve, Brake valve	Balmukunda, Arjun, Manish	3.5 hrs	Completed	**ACTIVE**	25-Feb-26	
2	**Bishnu Raj Subba**	321 39 111	Eicher-6 wheeler	26-Feb-26	10	WORKSHOP	Fuel injection pump pipe issue; Replaced		Alek, Manish	1.5 hrs	Completed	**ACTIVE**	25-Feb-26	
3	**Bhola Ram Tharu**	321 39 93	Eicher-6 wheeler	26-Feb-26	10	WORKSHOP	Brakes adjusted		Alek, Manish	25 min	Completed	**ACTIVE**	16-Feb-26	
Light Commercial Vehicle (LCV): 2														
4		341 03 30	Mahindra Bolero	25-Feb-26	11	WORKSHOP	Self assy issue; maintenance completed	Reparied self	Ram, Balmukunda	2.5 hrs	Completed	**ACTIVE**	-	
5	**Ankaman Rai**	341 03 38	Mahindra Bolero	26-Feb-26	10	TRT	Starting system malfunction rectified; dynamo serviced and restored to operational condition	Salvaged regulator	Ram	4 hrs	Completed	**ACTIVE**	25-Feb-26	
Hydraulic Excavator (HE): 4														
6	**Sunil Chaulagain**	321 45 38	Komatsu Excavator PC-210	26-Feb-26	10	SURGESHAFT	Bucket teeths, locks & pins replaced	Teeths, locks & pins	Kedar	1 hrs	Completed	18-Feb-26	19-Feb-26	
7	**Dipendra Sunuwar**	321 45 43	CAT Excavator 323D3	26-Feb-26	10	CRUSHER	Bucket replaced from 321 45 44; damaged bucket shifted to workshop for maintenance	Bucket,Shims, Grease	Sagar, Binod	30 min	Completed	**ACTIVE**	25-Feb-26	
8	**Milan Begha Lmibu**	321 45 40	CAT Excavator 323D3	26-Feb-26	10	WORKSHOP	Repaired bucket replaced	Repaired bucket, Shims	Kedar, Arjun	2 hrs	Completed	**ACTIVE**	25-Feb-26	
9	**Indra Bd. Shrestha**	321 45 29	XCMG Excavator 215C	25-Feb-26	11	WORKSHOP	Bucket cylinder damaged; Under Maintenance	Electrodes	Reman	7 hrs	Pending	**BREAKDOWN**	21-Feb-26	
Boomer: 1														
10	**Subash Shrestha**	321 39 126	Epiroc	26-Feb-26	10	WORKSHOP	Tube fitted; Tyres fitted; Hydraulic Pump bkts,flange issue attended; Placed Order; PR No: 782	Tube	Kedar, Alek, Indrajit, Arjun, Manish	5 hrs	Pending	**BREAKDOWN**	22-Feb-26	

27-Feb-26			DAILY MAINTENANCE REPORT M-tech = Mechanical Technician | E-Tech = Auto Electrician | L-Tech = Lube | W-Tech = Welder								M-Techs: 5	E-Tech: 1	L-Tech: 1	W-Tech: 3
S/N	Operator	Asset Code	Description	Date of B/D	B/D Days	Location	Breakdown Reason	Components	Technicians	Duration	Repair Status	Operational Status	Maintained	
High Commercial Vehicle (HCV): 3														
1	Prithi Rai	321 39 97	Eicher-10 wheeler	27-Feb-26	9	WORKSHOP	U bolts and leaf springs replaced	U bolt, Leaf springs	Arjun	4 hrs	Completed	ACTIVE	21-Feb-26	
2	Kriti Rai	321 39 86	Eicher- 10 wheeler	27-Feb-26	9	WORKSHOP	Multiple Engine mountings changed	Engine mounting	Balmukunda, Arjun, Manish	2.5 hrs	Completed	ACTIVE	26-Feb-26	
3	Bhola Ram Tharu	321 39 93	Eicher-6 wheeler	26-Feb-26	10	WORKSHOP	Brakes adjusted		Alek, Manish	25 min	Completed	ACTIVE	16-Feb-26	
Light Commercial Vehicle (LCV): 2														
4	Milan Bhujel	341 03 40	Mahindra Bolero	27-Feb-26	9	WORKSHOP	Comprehensive end-to-end servicing executed, including complete lubrication of all dynamic and load-bearing components.	Engine oil, Engine oil filter, Brake oil	Arjun, Manish	1.5 hrs	Completed	ACTIVE	19-Feb-26	
5	Ankaman Rai	341 03 38	Mahindra Bolero	27-Feb-26	9	TRT	Hub bearing changed, brake repair, Propeller shaft issue repaired		Ram	4 hrs	Completed	ACTIVE	26-Feb-26	
Boomer: 1														
6	Subash Shrestha	321 39 127	Epiroc	27-Feb-26	9	WORKSHOP	Sliding Bar and dowel changed	Slide bar, dowel	Kedar, Alek, Indrajit, Arjun, Manish	5 hrs	Completed	ACTIVE	22-Feb-26	
Hydraulic Excavator (HE): 2														
7	Suman Limbu	321 45 40	CAT Excavator 323D3	27-Feb-26	9	MAT	Comprehensive end-to-end servicing executed, including complete lubrication of all dynamic and load-bearing components.	Engine oil, Engine oil filter, Fuel filters, Air Filters, Hydraulic oil, Grease	Alek, Manish, Binod	1.5 hrs	Completed	ACTIVE	24-Feb-26	
8	Basanta Limbu	321 45 51	Kobelco Excavator SK380	27-Feb-26	9	SHINWA	Bolt fixed, Hard rail & foot step issue resolved		Sagar, Kedar	1.5 hrs	Completed	ACTIVE	24-Feb-26	